

Nissan Navara 2012+ Steering Wheel Control

If your Nissan Navara Steering Wheel Control is only half operating with the X-Series after the installation (cannot operate volume up and seek up), please follow the steps below to modify the exiting wiring loom.

- Cut orange with white trace - E7 - "lin-txd"
- Connect OEM plug side to brown with black trace -E20 - marked "KEY 2"
- Leave orange with white trace - E7 - free on the VMS unit side - tape to cover end

